


DS4208Quick Start Guide



STEP 1 - ATTACH CABLE TO SCANNER









Note: An audible click sounds when the shielded cable is inserted correctly.


STEP 2 - CONNECT CABLE TO A HOST



See Product Reference Guide for detailed information









STEP 3 - SET UP INTERFACE (Scan Host Bar Codes)

Important: Out of box, RS-232 and USB interfaces require no bar code scan setup. Bar codes are provided for complex programming or interface changes.









ADD AN ENTER KEY (CARRIAGE RETURN/LINE FEED)

To add an **ENTER** key after scanned data, scan all THREE bar codes below in numerical order.







ADD A TAB KEY

To add a **Tab** key after scanned data, scan all THREE **Enter** key bar codes above in numerical order then scan all FIVE bar codes below in numerical order.














Return to Factory Defaults



SET DEFAULTS







TROUBLESHOOTING

123Scan² is an easy-to-use, PC-based software tool that enables rapid and easy customized setup via a bar code or USB cable. For more information, visit:

http://www.motorola.com/123Scan2.

SCANNER INDICATIONS

LED Indications Standard Use

Off Green Scanner is on and ready to scan, or no power to scanne

Beeper Indications

Standard Use

Bar code is

Red

Transmission error

4 low beeps

Low/high beeps

Low/medium/high beeps Short beep Bar code symbol decoded Power up Parameter Menu Scanning

High/low beeps High/low/high/low beeps

Successful parameter setting

Input error; incorrect bar code,

Transmission error detected,

Troubleshooting

Scanner not working

No power to scanner Check system power

ensure power supply,

if required, is connected

Ensure that correct interface cable is used

Incorrect interface cable used

Scanner decoding bar code, but data not transmitting to host

Scan appropriate host parameter bar codes

Scanner not programmed for correct host interface

Interface/power cables are loose Ensure all cable connections

are secure

Interface cable is loose

Ensure all cable connections are secure

Scanned data incorrectly displayed on host

Scanner not programmed for correct host interface

Scan appropriate host parameter bar codes

Scanner not decoding bar code

Scanner not programmed Bar code unreadable for bar code type

Ensure scanner is programmed to read type of bar code being scanned

Ensure bar code not defaced: try scanning test bar code


Distance between scanner and bar code incorrect

Move scanner closer to or further from bar code

RECOMMENDED USAGE GUIDE - OPTIMUM BODY POSTURE

Avoid Extreme Wrist Angles

Keyboard parameter



Avoid Bending



Avoid Reaching



Health and Safety Recommendations

Ergonomic

Recommendations

Caution: In order to avoid or minimize the potential risk of ergonomic iniury follow the recommendations below. Consult with your local Health & Safety Manager to ensure that you are adhering to your company's safety programs to prevent employee injury.

- · Reduce or eliminate repetitive motion.
- Maintain a natural position.
- · Reduce or eliminate excessive force.
- · Keep objects that are used frequently within easy reach. · Perform tasks at correct heights.
- · Reduce or eliminate vibration.
- · Reduce or eliminate direct pressure. · Provide adjustable workstations.
- Provide adequate clearance. · Provide a suitable working environment.
- · Improve work procedures.

REGULATORY INFORMATION

© 2011 MOTOROLA, Inc. All rights reserved.

Motorola reserves the right to make changes to any product to improve reliability, function, or design. Motorola does not assume any product liability arising out of, or in connection with, the application or use of any product, circuit, or application described herein. No license is granted, either expressly or by implication, estoppel, or otherwise under any patent right or patent, covering or relating to any combination, system apparatus, machine, material, method, or process in which Motorola products might be used. An implied license exists only for equipment, circuits, and subsystems contained in Motorola products.

Power Supply

Warranty

Use ONLY a LISTED Motorola, Type no. PWRS-14000 (5.2Vdc, 850mA minimum), direct plug-in power supply, marked Class 2 or LPS (IEC60950-1, SELV). Use of alternative Power Supply will invalidate any approvals given to this unit and may be dangerous.

For the complete Motorola hardware product warranty statement, go to: http://www.motorola.com/enterprisemobility/warranty

Service Information

If you have a problem using the equipment, contact your facility's Technical or Systems Support. If there is a problem with the equipment, they will contact the Motorola Solutions Support at:

For the latest version of this guide go to: http://supportcentral.motorola.com.

Waste Electrical and Electronic Equipment (WEEE)

English: For EU Customers: All products at the end of their life must be returned to Motorola for recycling. For information on how to return product, please go to: http://www.motorola.com/recycling/weee.

http://www.motorola.com/recycling/weee.
Butgarth 23 avenue o EC Cice, quis an encewar wa sware screw popyrar spatial ga ce spaugir se Motorola sa payamapane, 3a wybopasque on oco o spaugirero wa noogare, sons oragene se agene, http://www.motorola.com/recycling/weee.
Celter Pro Zakaway EU V Seberny produkty en unite po socional sjelch živonosom stratit společnost Motorola k negykato, Informace o zpisobu vrácení produktu najdele na webové stárnos: http://www.motorola.com/recycling/weee
Dansic Tik under EU. Ale produkter skal returneres BI Motorola til recikulering, nár de er utiljet. Las oplyanjeme on returnering af produkter pá: http://www.motorola.com/recycling/weee.

http://www.miotoroia.com/recycling/weee.

Doutsch: Für Kunden innerhalb der EU: Alle Produkte müssen am Ende ihrer Lebensdauer zum Recycling an Motorola zurrückgesandt werden, Informationen zur Rücksendung von Produkten Inden Sie unter http://www.motoroia.com/recycling/weee.

Podukań fiden Ślie ulner http://www.motorola.com/recycling/weee.
EAnywech Ton zhingr.cmy E.E.; Ole na prokievn, om take, no fisenszek guler,
toc, ngóm tru exmercieova omy Motorola va osaciskulom, fila mapowinszek ninpopopisz
ograficia i zm. remopopi neky ngolokie, menzelekie m. selekievn
http://www.motorola.com/recycling/weee ono Apolieuo.
Edicielie Ciki Korola tulke nende eluela loppodes tagastada tasaksaudamise
eesmärgil Motorola'ile. Lisainformatsiooni saamiseks toote tagastamise kohta külastage

palun aadressi: http://www.motorola.com/recycling/weee.

palun aadressi: http://www.motorola.com/recycling/weee.
Enginte/ Para clarites en la luhin Europea: todos ko products deberin entregance a
Motorola al final die su ciclo de vida para que sean recladors. Si desea mate información
sobre como devider-un producto, vieles http://www.motorola.com/recycling/weee,
Fangais: Cilente del Tuno Européanne: Tous les produtes en fin de optio de viel doient
der reformés à Motorola pour recyclage. Pour de plus amples informations sur le retour de
produits, constaite: http://www.motorola.com/recycling/weee.
Balance per i clienti dell'Utili unit produit de la more giunt al terreme del repetitivo ciclo di
vida devieno essere resistatia à Motorola al finer d'consertine il riciclagajo. Per informazion
vida devieno essere resistatia d'attoria al finer d'consertine il riciclagajo. Per informazion
tota devieno essere resistatia d'attoria al finer d'consertine il riciclagajo. Per informazion
tota devieno essere cinstituta d'attoria al finer d'consertine il riciclagajo. Per informazion
tota devieno essere constituta d'attoria al finer d'attoria produita riciclagajo. Per informazion
http://www.motorola.com/recycling/weee.

Libreaux E Si kentien: vas produita pez lo kalposáñas nituza biégam'n janogada atpakaj
Motorola otracegiaj plansfadel, cia iagitui eliormazioj par produita nogládásna Motorola,
lidizu, skalet: http://www.motorola.com/recycling/weee.

Lotukę ES vartotojams: visi gaminiai, pasibaigus jų eksploatacijos laikui, turi būti grąžinti utlizuoti į kompaniją. "Motorols". Daugiau informacijos, kaip grąžinti gaminį, rastie: http://www.motorola.com/recycling/wee.

Magger, Az EU-kow skistiktosis. Mitomi briknement temniekst a Motorola valislaithoto kail ajustanti vijanbasznostisto oslibati. A termik visaszaitustialistienis modigival kapcsolatos durhvialdiskieti tištogassona el a http://www.motorola.com/recycling/weee weboldara.

Mati. Chali kijanti FUE: lypodoti kotha i joun wastu hathar tai Paligia tai viziu taghhom, rido vigu rittomat ghand Motorola ghar-ticitidagi. Obal aktar taghrif dwar kifghandek tirritoma propodit, jaik jolipabik ziur. http://www.motorola.com/recyclinni/was

Forodott, jekk jogňábok žur: http://www.motorola.com/recycling/weee Nederlands: Voor klanten in de EU: alls producten dienen aan het einde van hun levensduur naar Motorda le worden tengezonden voor recycling. Raadpleeg http://www.motorola.com/recycling/weee voor meer informatie over het terugzenden van producten.

Jerugaredes van producter.

Politik filerna i zobazaru Unifi Europejskiej: Produkty wycofane z eksploatacji należy zwrócó do firmy Motoroki w celu ich ułydzacji, Informacje na lemat zurotu produktów znajduja się na strone internatowej http://www.motorolia.com/recycling/weee.

Produgate Pzna elinesia du Et Listos os produta no finie dwał dwem ser devolvidos a Motorob para reciclagem. Para obte informações softe como devolver o produd, visite http://www.motorolia.com/recycling/weee.

Romineze Pentru clienti din UE: Toate produsele, la sifansi durate la pré funcionare, testain eliumale a Motorola pentru recicling /weee.

Romineze Pentru clienti din UE: Toate produsele, la sifansi durate la pré funcionare, testain eliumale a Motorola pentru recicling /weee.

Sworther Positicarilor z kan izili. EVIder vietblo musia se for ou pelvutuli dobri chi

Slovendina: Pre zákazníkov z krajín EU: Všetky výrobky musia byť po uplynutí doby ich životnosti vřatené spoločnosti Motorola na recykláciu. Bližšie informácie o vřátení výrobko nájdete na: http://www.motorola.com/recycling/weee. najorite ne. http://www.motoroia.com/recycing/weee. Stovenski 2 kupov b U: visi zdoki se monijo po poteu šivljenjske dobe vmiti podjetju Motorola za recklušo. Za informacije o vračilu izdekla obišdite: http://www.motorola.com/recycling/weee. Suone 3-sakkas Euroopan unionin alueelis: Kalkik bustede on paluetativa kieriletitaviskis Motorola-yničios. Anu tuotatis ei einiš kirjesti. Lisiletiopi tuotien palautativas kieriletitaviskis Motorola-yničios. Anu tuotatis ei einiš kirjesti. Lisiletiopi tuotien palautativas siano osoitiesess http://www.motorola.com/recycling/weee. Svenska: For kunder inom EU: Alla produkter som uppnått sin livslängd måste returneras till Motorola för återvinning, Information om hur du returnerar produkten finns på http://www.motorola.com/recycling/weee. Türkçe: AB Müşterileri içir. Kullanım süresi öldən tüm ürünler geri dönüştürme için Motorola'ya iade edilmelidir. Ürünlerin nasıl iade edileceği hakkında bilgi için lülfen şu adresi ziyaret edin:



MOTOROLA, MOTO, MOTOROLA SOLUTIONS and the Stylized M Logo are trademarks or registered trademarks of Motorola Trademark Holding, LLC and are used under license.





Scanner Labeling



Regulatory Information

This device is approved under Motorola, Inc. ("Motorola").

This guide applies to Model Number: DS4208

All Motorola devices are designed to be compliant with rules and regulations in locations they are sold and will be labeled as required. Local language translations are available at the following website: http://supportcentral.motorola.com

Any changes or modifications to Motorola Technologies equipment, not expressly approved by

Motorola, could void the user's authority to operate the equipment. Antennas: Use only the supplied or an approved replacement antenna. Unauthorized antennas modifications, or attachments could cause damage and may violate regulations

LED Devices

Complies with IEC/EN60825-1:2001 & IEC/EN62471:2006

For devices with Class 1M LEDs the following label is used

Radio Frequency Interference Requirements -FCC



Note: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC rules These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not

installed and used in accordance with the instructions, may cause harmful interference to radio communications. However there is no quarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna · Increase the separation between the equipment and receiver
- . Connect the equipment into an outlet on a circuit different from that to which the receiver is connected
- Consult the dealer or an experienced radio/TV technician for help

Radio Frequency Interference Requirements - Canada This Class B digital apparatus complies with Canadian ICES-003.

Cet appareil numérique de la classe B est conforme à la norme NMB-003 du Canada



Statement of Compliance

Motorola hereby declares that this device is in compliance with all the applicable Directives, 2004/108/EC and 2006/95/EC. A Declaration of Conformity may be obtained from http://www.motorola.com/doc

TURKISH WEEE Statement of Compliance

EEE Yönetmeliğine Uygundu

Japan (VCCI) - Voluntary Control Council for Interference Class B ITE

この装置は、情報処理装置等電波障害自主規制協議会(VCCI)の基準に基づくクラスB情 報技術装置です。この装置は、家庭環境で使用することを目的としていますが、この装置がラジオやテレビジョン受信機に近接して使用されると、受信障害を引き起こすことがあります。 取扱説明書に従って正しい取り扱いをして下さい。

Korea Warning Statement for Class B ITE

기 종 별	사 용 자 안 내 문
B급 기기	이 기기는 가정용(B급)으로 전자파적합등록을
(가정용 방송통신기기)	한 기기로서 주로 가정에서 사용하는 것을 목적
	으로 하며, 모든 지역에서 사용할 수 있습니다.